

# Mill Schedule

| Week of          | Mill 1  | Mill 2   | Mill 3                                      |
|------------------|---|--|---|
| <b>March 11:</b> | RT 1X3<br>238 Round<br>200 Round  | 166 RO<br>166EE<br>166OO<br>166D<br>1050 (Light) | RT 2X4<br>300 Square                        |
| <b>March 18:</b> | 190 Round<br>150 Square   | 1166 RR<br>166 RN                                | RT 2X3<br>300 Round<br>287<br>238           |
| <b>March 25:</b> | RT 1X2<br>166 H<br>125 Square<br>1315<br>125 Round<br>100 Square<br>1050 H<br>100 Round | 166 RO<br>166EE<br>166OO<br>166D<br>1050 (Light) | 500 Round<br>RT 2X6<br>400 Square<br>BT 450 |
| <b>April 1:</b>  | 287 Round<br>275 Round<br>200 Square  | 166 RR<br>166 RN                                 | RT 2X5<br>BT400                             |

**\*\*All orders for must be placed 5 business days prior to mill cycle. Minimum order may be required\*\***

**\*\*Mill Schedule is subject to change\*\***

1-800-527-8616/ Phone

1-903-572-2798/ Fax

[steelsales@priefert.com](mailto:steelsales@priefert.com)

[www.priefertsteel.com](http://www.priefertsteel.com)